





EDL-S







Page 17





Page 16




Page 17




New




Page 17



Page 15










Pages 6-9 + 13-19





Pages 10-12 + 13-19

1






2






3











4

BDX








5








6

1












3




6



7a








7b
















8

BFX
1000U



















15






GPL / GPU / GTL / GDL



16



17



| | |
|---|---|
| AR: VELUX Argentina S.A. 348 4 639944 | HU: VELUX Magyarország Kft. (06/1) 436-0601 |
| AT: VELUX Österreich GmbH 02245/32 3 50 | IE: VELUX Company Ltd. 01 848 8775 |
| AU: VELUX Australia Pty. Ltd. 1300 859 856 | IT: VELUX Italia s.p.a. 045/6173666 |
| BA: VELUX Bosna i Hercegovina d.o.o. 033/626 493, 626 494 | JP: VELUX-Japan Ltd. 0570-00-8145 |
| BE: VELUX Belgium (010) 42.09.09 | LT: VELUX Lietuva, UAB (85) 270 91 01 |
| BG: VELUX Bulgaria EOOD 02/955 99 30 | LV: VELUX Latvia SIA 67 27 77 33 |
| BY: FE VELUX Roof Windows (017) 217 7385 | NL: VELUX Nederland B.V. 030 - 6 629 629 |
| CA: VELUX Canada Inc. 1 800 88-VELUX (888-3589) | NO: VELUX Norge AS 22 51 06 00 |
| CH: VELUX Schweiz AG 0848 945 549 | NZ: VELUX New Zealand Ltd. 0800 650 445 |
| CL: VELUX Chile Limitada 2 953 6789 | PL: VELUX Polska Sp. z o.o. (022) 33 77 000 / 33 77 070 |
| CN: VELUX (CHINA) CO. LTD. 0316-607 27 27 | PT: VELUX Portugal, Lda 21 880 00 60 |
| CZ: VELUX Česká republika, s.r.o. 531 015 511 | RO: VELUX România S.R.L. 0-8008-83589 |
| DE: VELUX Deutschland GmbH 01806 / 33 33 99 Festnetz: 0,20 €/Anruf Mobilfunk: max. 0,60 €/Anruf | RS: VELUX Srbija d.o.o. 011 20 57 500 |
| DK: VELUX Danmark A/S 45 16 45 16 | RU: ZAO VELUX (495) 737 75 20 |
| EE: VELUX Eesti OÜ 621 7790 | SE: VELUX Svenska AB 042/20 83 80 |
| ES: VELUX Spain, S.A. 91 509 71 00 | SI: VELUX Slovenija d.o.o. 01 724 68 68 |
| FI: VELUX Suomi Oy 0207 290 800 | SK: VELUX Slovensko, s.r.o. (02) 33 000 555 |
| FR: VELUX France 0821 02 15 15 0,119€ TTC/min | TR: VELUX Çati Pencereci Ticaret Limited Şirketi 0 216 302 54 10 |
| GB: VELUX Company Ltd. 01592 778 225 | UA: VELUX Ukraina TOV (044) 2916070 |
| HR: VELUX Hrvatska d.o.o. 01/5555 444 | US: VELUX America Inc. 1-800-88-VELUX |